

---

**Alaska Railroad Corporation**  
**Summary List of Suspect Asbestos Materials**

Site: Anchorage  
Bldg ID: 11491, Diesel Fuel Pump Hse.  
485 Ocean Dock Rd  
Anchorage, AK

HM	Material Description	Floor	Location(s)	Contains Asbestos	Lab Results
1	Miscellaneous, Cement Board		Walls and Ceiling	Yes	
2	Roofing Tar and Felt,		Roofing Felt	Presumed	
3	Ceiling/wall Texture, White above ceiling		Report# 053202, Sample #BPEQD- A	NO	